

SPATA Welding Gloves Sizing Chart

To measure, wrap a flexible tape measure around your dominant hand just below the knuckles (excluding the thumb). If you're between sizes, choose the larger size for comfort or the smaller size for a snug fit.






Glove Size
Hand Circumference (cm)




S	M	L	XL	XXL
18 – 20 cm	20 – 23 cm	23 – 25 cm	25 – 28 cm	28 – 30 cm

Selecting the right SPATA Glove

TIG

				EN 388	EN 407	Sizes
TIG	TIG Tough SPTI05		A Tough, Hard-Wearing TIG Glove	2X31B	412X4X	M, L, XL
	TIG Feel SPTI10		Highest Level of Touch & Feel	2X31B	412X4X	S, M, L, XL
	The Hybrid SPTI15		More Heat & Cut Protection	3X33D	423244	S, M, L, XL

HEAT

				EN 388	EN 407	Sizes
HEAT	All-Rounder SPHE05		High Heat Protection	4X44D	43334X	L, XL, XXL
	Inside Out SPHE10		High Comfort with Softer Feel	3X43F	413244	L, XL, XXL
	Pro HD SPHE15		Ultimate Professional's Welding Glove	3X42F	423244	M, L, XL, XXL